





QT61072V03

Canon

EN



Please ensure the printer remains flat after initial setup and is **NOT** turned upside down or on its side, as ink in the printer may leak.

Notice

Avertissement

Aviso

Aviso

Σημείωση

Upozornění

Megjegyzés

Uwaga

Vyhlasenie

Уведомление

Märkus

Paziņojums

Pastaba

注意

Obvestilo

Uyarı

Повідомлення

Съобщение

Notă

Napomena

ملاحظة

注意

주의

អំពាវនាវ

Pemberitahuan

Thông báo

Ескерту

Ծանուցում

Эскертүү

The remaining ink level notification function works from initial printing to the time when one of the inks reaches the lower limit line shown on the ink tank. For the remaining ink level notification function to work appropriately, each ink tank must be filled with entire contents of the corresponding color ink bottle bundled with the printer before printing. After the initial filling, if either of the ink tanks is refilled before the remaining ink level reaches the lower limit line, a significant error may occur in the accuracy of the remaining ink level notification function. If you want to refill an ink tank before the remaining ink level reaches the lower limit line, be sure to follow the procedure in the manual.

Note: To check the remaining ink level, visually inspect the remaining ink in the ink tank.

Transporting the Printer

Put the printer into a plastic bag and seal the bag tightly.